

Sat. 20 Nov. 1943

- 0715 Red to ops
- 0820 Wind SW/6; vis 0; R/W NE-SW
- 1230 On Duty Harry E. McClellan
- 1300 Red to ops
- 1335 Routine inspection of aid room
- 1600 issued cans "WJ"
- 1822 Beacon set up everything in order
- 1823 Flarepath laid SW/NE, net consulted
- 1955 Bundit crew reports beacon not flashing properly, beacon flashing a steady red.
- 2000 W/FC informed of condition of beacon. They advise us to leave beacon and if it cannot be repaired tomorrow to inform AS-4.
- 2005 Beacon recalled,