VIASHINGTON 5987
$\frac{1}{10000000000000000000000000000000000$
IMPORTANT: This report will be compiled in triplicate by each Army Air Forces organization within 48 hours of the time an aircraft is
officially reported missing.
1. ORGANIZATION: Location AAF Station 111 ; Command or Air Force 8th Group 306th Bomb (H) ; Squadron 423rd Bomb (H) Bataalaaata
2. SPECIFY: Point of Departure Thurleigh, England ; Course as prescribed Intended Destination HAMBURG, GERMANY ; Type of Mission Heavy Bomb
3. WEATHER CONDITIONS AND VISIBILITY AT TIME OF CRASH OR WHEN LAST REPORTED:
4. GIVE: (a)Date 20 Jun/44; Time 0928 ; and Location Vicinity of Hamburg.
of last known whereabouts of missing aircraft. (b) Specify whether (I) Last Sighted; () Last contacted by Radio;
() Forced Down; () Seen to Crash; or () Information not Available.
5. AIRCRAFT WAS LOST, OR IS BELIEVED TO HAVE BEEN LOST, AS A RESULT OF: (Check only one () Enemy Aircraft; (X) Enemy Anti-Aircraft; () Other Circumstances as
follows
A TEGENER, Man Model and Series - In A A E Conicl Without
6. AIRCRAFT: Type, Model and Series <u>B-17-G</u> ; A.A.F. Serial Number <u>42-97250</u> X 7. ENGINES: Type, Model and Series <u>R-1820-97</u> ; A.A.F. Serial Number (A) SW-011800
(b) SW-011759 ;(c) SW-011843 ;(d) SW-011772
8. INSTALLED WEAPONS (Furnish below Make, Type and Serial Number) (a) <u>s-1199497</u> ; (b) <u>s-1199536</u> ; (c) <u>s-1200095</u> ; (d) <u>B-1299943</u>
(e) B-1299561 ; (f) BLC-1531246 ; (g) BLC-1531251 ; (h) S-1199903 /
9. THE PERSONS LISTED BELOW MERE REPORTED AS: (a) Battle Casualty or (b)
10. NUMBER OF PERSONS ABOARD AIRCRAFT: Crew 9 ; Passengers 0 ; Total 9
(Statting with pilot, furnish the fellowing particulars: If more than 10
persons were aboard aircraft, list similar particulars on separate sheet and attach original to this form).
Name in Full Serial
1. Pilot -Pilot (Last Name First) Rank Number
1. pilot -pilot Latham. Derrill IV Ist It 0-748434 RTD 2. pilot - Co-Pilot Porter, Ellis 0. 2nd Lt 0-758723 RTD Chel
Navigator - Navigator - Nuttall, Andrew (NMT) 1 at It -0-694395 21.0
<ul> <li>Bombardier - Bombardier Nose Gun. Bryant. Harold A. Ar. lat Lt .0-679604 . Dc.20</li> <li>Aer. Eng. Gun Top Turret Gun Epps. Bryan E. V. E. Sgt 18043684 RT D</li> </ul>
6. Radio Opr - Radio DprBreckels, Winston J. T/Set Pup 36501774
7. Arm. Gun Ball Turret Gun Reed, Harold La S/Set -34049041 Deg 0 -
8. Arm. Gun Waist Gunner KIH They Walsh. Edward D. 18219507 1200- 9. Arm. Gun Tail Gunner KIH They Walsh. Edward D. 190 Gpl 32734924 Dest
10.
11. IDENTIFY BELOW THOSE PERSONS WHO ARE BELIEVED TO HAVE LAST KNOWLEDGE OF AIR- CRAFT, AND CHECK APPROPRIATE COLUMN TO INDICATE BASIS FOR SAME.
Check Only One Column
Name in Full
(Last Name First) Rank Number Radio Sighted Crash Landing
1. Mitchell, William G. Jr 1st Lt 0-813938 x
2
12. IF PERSONNEL ARE BELIEVED TO HAVE SURVIVED, ANSWER YES TO ONE OF THE FOLLOWING
STATEMENTS: (a) Parachutes were used yes; (b) Persons were seen walking away fr- om scene of crash ;or(c) Any other reason(Specify)
13. ATTACH AERIAL PHOTOGRAPH, MAP, CHART, ORSKETCH, SHOWING APPROXIMATE LOCATION WHERE
AIRCRAFT WAS LAST SEEN.
14. ATTACH EYEWITNESS DESCRIPTION OF CRASH, FORCED LANDING, OR OTHER CIRCUMSTANCES PERTAINING TO MISSING AIRCRAFT.
15. ATTACH A DESCRIPTION OF THE EXTENT OF SEARCH, IF ANY, AND GIVE NAME, RANK AND
SERIAL NUMBER OF OFFICER IN CHARGE HERE



HEADQUARTERS 306TH BOMBARDMENT GROUP (H) Office of the Commanding Officer United States Forces

> APO 557, 21 June, 1944.

SUBJECT: Eye witness account of incidents pertaining to Aircraft # 42-97250, Pilot 1st Lt D.L. LATHAM, Missing in Action 20 June, 1944.

TO:

Suce !!

Commanding General, Hq., First Bombardment Division, APO 557.

1. According to 1st Lt William G. Mitchell, Jr., 0-813938, Pilot of an aircraft in the same formation the following is an account of what happened to Aircraft No. 42-97250, Pilot 1st Lt D.L. LATHAM:

"Our aircraft #250 - G, Pilot Latham was hit by flak over target after bombs away. Fire broke out on the two inboard engines and spread over nose to Radio Room. Aircraft peeled out, side-slipping to the left and went straight down. One crew reports seeing waist door off. One crew reports one chute. Aircraft was observed to go to pieces in the air."

For the COMMANDING OFFICER:

Illie JL J. HAILLIE. Captain, Air Corps.

Asst. Adjutant.

