

JAN 13

- 0800 Met office advises wind WNW 5-10 miles
- 0800 Ops advised as to obstructions on runways, perimeters etc.
- 0800 H.O.W. Lt Nagle - On Watch L.B. Hartnell, Capt.
- 1030 Fort landed S to N and not as instructed SE to NW. Ran off end of runway & got stuck.
- 1230 off watch L.B. Hartnell, Capt.
- 1230 Took over watch JF Nagle Lt.
- 1244 Col. Armstrong instructs that DF station pass message on WT. to all Bramble a/c check all mike buttons. DF advised
- 1630 Signals advise SBA. not to be used while main runway is under construction.
- 1630 Met advises wind in evening will be from SE. Flare path being laid [redacted] N.W. to SE.
- 1830 Handed over watch Lt Nagle - On Watch L.B. Hartnell, Capt.