

March 5, ~~February~~ Sunday

- 0710 Crew to live and ops.
- 0820 Made routine inspection of airframe.
- 1030 SBA system went out.
- 1100 SBA working again
- 1105 R/W changed to 06.
- 1115 S.B.A. off again - Electricity off.
- 1145 SBA <sup>off</sup> again -
- 1215 Briefing for Summary mission at 1315
- 1220 On Duty Lt. Perman
- 1330 attended Briefing - Data follows: R/W = 06  
Route: Base - Mable Hope, 5345N - 0120E. Cleared  
 thru 1st Dir. 7/C. E.T.D. 1430 - E.T.A. 1700  
all necessary calls made for take-off.
- 1700 Issued Carab 1K to Puncht Crew.
- 1730 <sup>(445)</sup> Manet G - Capt Witt eliminated one (1) each Person  
(temporarily) in joining part tower. One each  
Wiretip - Right - B-17-G - #445 - also eliminated.
- 1800 Hauptair laid SW/NE. Met. Consulted.
- 1920 Routine inspection of gen. drome area.