

25, DECEMBER, MONDAY - CHRISTMAS DAY

0700 C.O. of 355 ft. Exp. requests through 40 C.B.W. that we clear P-51 #630 as soon as possible. 40 C.B.W. informed weather zero zero here and first possible break around noon.

0740 On duty Lt. Carlile off Capt. Peterman

0750 Red to div. and ops. Field fogged in NW and perimeter icy.

0850 Steple Warden called about P-51-630. Wanted to know if we could get off this morning. Explained our position. Steple Warden requests we remain here until further word from ^{them} ~~us~~.

0915 Insp. ops. requests we call all stations where our we are with exception of Campfield, Wing and Detach and tell crews they will have to remain at stations where they are. J.O.D. asked to call, said they would.

0925 Made routine inspection of gen. drome area - R/W's and perimeter tracks icy

17:30
18:00 Lt Klein on duty, Carlile off.
Inspected airdrome. Obstruction lights placed.