

1730 ON duty - Lt. BASS Off - Lt. CARRINE.
 1740 Inspected AIRFIELD - free from obstructions
 25 MAY '45

0700 RW changed 30. W.I.P. on RW 24.
 0800 On duty Lt. Carille Off duty Lt. Bass
 0805 Inspected RW's + perimeter - W.I.P. main RW
 1215 Off duty Lt. Carille - on Lt. Blaise
 1300 Queued action taken on B-26 # 730 then
 F.I. ops. UXBIDGE. B-26 was airborne
 to us from Y-9 at 0830 B. Implied at 12
 1830 On Lt. Carille Off Lt. Blaise
 1835 Cancelled Queued action on B-26 730
 through Uxbridge, div. F.I.
 1910 Inspected airframe - S - RW 24-0
 O.K. for use tonight if necessary
 2040 New duty officer phone number
 26, continental phone is 131

JANUARY 26 MAY 1945

0800 Off duty Lt. Carille - on Lt. Blaise
 0805 Inspected airframe - main RW & RW 30
 clear of obstructions & desirable.
 0830 Give permission for workmen to work on
 main RW. Work will be in progress
 all day.
 0905 By Ops. wants the pilots of 450 - 539 - 570
 to report to Ops. if any of the strip
 land today - from Y-94. Immediately
 0910 Capt. Sluman by Ops. OK'd Col. Coulter flight
 of Y-17, number # 4. Field Aid.
 0915 368th Ops. scrubbed transition.

1230 ON duty - Lt. BASS Off - Lt. BLAISE
 1240 Inspected AIRFIELD - free from obstructions
 1830 Inspected AIRFIELD - free from obstructions
 2030 X-COUNTRY MIGHT FLYING SCRUBBED -
 CAPT. MURPHY.

27 MAY '45

0800 Inspected Airfield - free from obstructions.
 1230 On Lt. Carille Off Lt. Bass
 1300 Inspected RW's + Perimeter - S
 1430 RW changed to 30 Wind 10-15 mph.
 1530 Tiger Math # 80 landed and broke strut on

port side. Go from Lywell - Name base called.

1510 R/W back to R/W 24 Wind W-10

1625 C-47-184 take off for Churchinton. Go will be back in morning to pick up leave personnel. Pilot will call before T.O. for us

1830 Off duty Lt. Carlisle - on Lt. Blaise

1835 Made airbase inspection - main RW & perimeter clear of all obstructions & serviceable

2000 HAPS. Gove informed us HIC 724 of 42nd Sq will remain overnight at Y-11. Notified by Capt & 1st Lt B. Dow. J.P. & 42nd Sq.

MONDAY May 28, 1945

On duty Lt. Carlisle Off Lt. Blaise

0740 Capt. Sherman O.N'S work on perimeter track in 368th Area, and keep workmen off of main RW. Lammace & work on 30 RW

0910 Capt. Brock, Communications States per tele type from USAO, that 505-51 will be operated by request only - thru out 24 hour period

0950 Inspected airbase - W.L.P. R/W 30 rest of airbase - S

1225 Off duty Lt. Carlisle - on Lt. Blaise

1240 Made airbase inspection - main RW & perimeter clear of all obstructions & serviceable

1440 Sgt. Gove informed us Col. Upland will remain overnight at Longford Lodge. Informed 1st Lt B. Dow.

180 On Lt. Carlisle Off Lt. Blaise

1830 Inspected airbase - S

2240 C-46 expected from B-54 tonight or tomorrow morning. When C.T.A. or Go arrives. Maj. France of 40th C.B.W. is to be notified

2250 Dir. asks us to light up airbase, considerable amount of flying in area. Go on ^{holding time} airbase

TUESDAY - 29 MAY 1945

0700 Off duty Lt. Carlisle - on Lt. Blaise

0720 Made airbase inspection - main RW & perimeter clear of obstructions & serviceable

1230 On Duty - Lt. BASS Off - Lt. BLAISE