

8 May 1944

0415 Attended briefing: QFF 30.05

S.E. 0544 YY Using r/w 24 periods

Taxi 0602
~~0555~~ RY

T.O. 0612
~~0605~~ GG 367 - 368 - 369 - 42

UJB - TVN - UAW - PL

0710 Cleared Cycle Ship thru division.

0800 On duty Lt. Cable

0830 Inspected airfield

1130 M/sgt, from 8th district WBS came to inspect condition of our airfield. Says condition pretty bad. Will be back in Wuk on ten days

1230 On duty Capt. Bradbury,

1300 Made necessary calls for return of ops. all to be stationed at 1400

1330 Inspected R/W's. Perimeter will be serviceable for landing of ops - use caution in crossing R/W 30.

1500 Briefed QFF for 9 May

Phone briefed QFF to be phoned to Communications each day at 1500 hrs.

2020 We are alerted.

2040 Inspected R/W + perimeter.

2050 Flame path on 24.

2150 Extra # of AT's on 18.

2205 Fuse blown on N-S flame path lighting.

2240 N-S flame path now serviceable.